ECS Configuration		icət			,	age 1 or /	Pages
CCR No. 48-063	Z Logged (Date	5/22/98	Rev. — Request T		ype CC/C	
Priority Routine	Urgent	Er	nergency x	Affected Release		Change Clas	ss /N
Title (description) Files to VATC for test of NCR ECSed15037							
Documents Affected				Source Nos (RID, N	NCR, Action It	em, GSFC CCF	R, etc.) or
None				rech Reference			
Tione							
RTM Change Start New Baseline							
Problem The testing of the fill VATC.	x for NCR ECS	ed156	037 requires	that a file be deliv	ered and i	nstalled in t	he ·
Proposed Solution 1. Ship the following file from the nightly build output to the SMC for delivery to VATC only: EcCoAssist. 2. Install file under /tools/common/ea to replace existing file.							
Impact Analysis:							
Organizations Affected:	воо 🔲	Co	ontracts	ECS Chief Eng	FOS _	Ма	. ○ □
Procurement	∞ □		Rel. Dev 🗓	Rel. A	Rel. C	SCDO Arc	:h. 🔲 📗
Science Off	Security	Sub	ocontrot	Sys. Eng	Sys Verf Acpt		
Cost:	None 🗓		Small	Medium	Large		
Schedule:	None C	(No	ot exceeding \$100,000) Other	(\$100,000 to \$500,000)	(Over \$500,000)		
Additional LOC	None		Other	Man-Month	ie.		
_			Λ (
Materials		\bigcirc	1.			100	
Originator John Ujha	zy x0468	\geq	Jan.	Jozep	<u> 51°</u>	22/97	<u> </u>
		Sign	eture		,	ا سرا	Pate
Office Dovelopment	Office Manager	Sign	ature 1	Dill	5[7	n/58	Date
Disposition	Approved 🔀	Ap	proved w/Com	nent Forw	ard	Disapprove	ed 🔲
Comments:	/		_	_			
C	CB Chairperson	Siado		Jen	L	5/2	2/98
CM01OC96		Signatu				/	ECS
CIVIOTOCSO		/_					

ORIGINAL

CM-NP